



Radon Mitigation Quality Assurance Test

The goal of this test is to assure functionality of installed radon mitigation systems in the building. Two alternate occupied rooms from the list below will be tested yearly.

Building Information	2642	District	ASD-W
Building Name:	Gibson-Neill Memorial School		
Year constructed	2013	Phase	7
Street Address:	67 Wyngate Drive		
City:	Fredericton		
Ventilation System	Y \ N	Mitigation System	Y \ N
Facilities Manager:	Telephone Number		
Name of Person Placing Detectors:			

Instructions:

Installation

- 1) Choose two rooms below, if "R" is indicated in front of the room number, this room must be tested.
- 2) Write the detector number on the corresponding room number line
- 3) Write the installation date on the corresponding room number line.
- 4) Write the installation date on the detector (Start Date).
- 5) Fax a copy of this sheet after the installation has been complete to (506) 444-5529 or email to pascal.landry@gnb.ca.
- 6) Keep this page for the duration of the test and return with detectors.

Collection

The duration of the test will be 90 days.

- 1) Collect the two detectors after 90 days
- 2) Write the collection date on the detector.
- 3) Write the collection date on the corresponding line below.
- 4) Return the two detectors and this form to:

**Att: Pascal Landry
Educational Facilities
250 King Street, Place 2000
Fredericton, NB
E3B 9M9**

Gibson-Neill Memorial School

Room No.	Serial Number	Installation Date day/month/year	Collection Date day/month/year	Result Bq/m ³	Uncertainty
105	323473	06/04/2016	27/06/2016	37 ± 8%	
191A	323474	06/04/2016	27/06/2016	48 ± 7%	
116A	323475	06/04/2016	27/06/2016	41 ± 8%	
190	323476	06/04/2016	27/06/2016	59 ± 7%	
189	323477	06/04/2016	27/06/2016	44 ± 8%	
187	323478	06/04/2016	27/06/2016	44 ± 8%	
186A	323479	06/04/2016	27/06/2016	52 ± 7%	
186	323480	06/04/2016	27/06/2016	7 ± 15%	
186	323481	06/04/2016	27/06/2016	44 ± 8%	
186	323482	06/04/2016	27/06/2016	48 ± 7%	

Fax form to (506) 444-5529 after installation of detectors.

Return completed document after collection of detectors

Gibson-Neill Memorial School					
Room No.	Serial Number	Installation Date day/month/year	Collection Date day/month/year	Result Bq/m ³	Uncertainty
184	323483	06/04/2016	27/06/2016	85 ± 6%	
183	323484	06/04/2016	27/06/2016	63 ± 7%	
181	323485	06/04/2016	27/06/2016	52 ± 7%	
172	323486	06/04/2016	27/06/2016	44 ± 8%	
166	323487	06/04/2016	27/06/2016	56 ± 7%	
164	323488	06/04/2016	27/06/2016	63 ± 7%	
163	323489	06/04/2016	27/06/2016	89 ± 6%	
161	323490	06/04/2016	27/06/2016	67 ± 6%	
160A	323491	06/04/2016	27/06/2016	104 ± 5%	
160A	323492	06/04/2016	27/06/2016	100 ± 5%	
157	323493	06/04/2016	27/06/2016	78 ± 6%	
155	323494	06/04/2016	27/06/2016	74 ± 6%	
145	323495	06/04/2016	27/06/2016	44 ± 8%	
143	323496	06/04/2016	27/06/2016	52 ± 7%	
142	323497	06/04/2016	27/06/2016	78 ± 6%	
140	323498	06/04/2016	27/06/2016	74 ± 6%	
139	323499	06/04/2016	27/06/2016	118 ± 5%	
137	323500	06/04/2016	27/06/2016	170 ± 4%	