

Radon Mitigation Quality Assurance Test

The goal of this test is to assure functionality of installed radon mitigation systems in the building. Two alternate occupied rooms from the list below will be tested yearly.						
Building Information	2641	Distric	ct ASD-W			
Building Name:	Bliss Carmen Middle School					
Year constructed	2009	Phase	4			
Street Address:	615 Kimble Drive					
City:	Fredericton					
Ventilation System Y \ N		Mitigation System	Y\N			
			Telephon Number			
Facilities Manager:						
Name of Person Placing Detectors:						

Instructions:

Installation

- 1) Choose two rooms below, if "R" is indicated in front of the room number, this room must be tested.
- 2) Write the detector number on the corresponding room number line
- 3) Write the installation date on the corresponding room number line.
- 4) Write the installation date on the detector (Start Date).
- 5) Fax a copy of this sheet after the installation has been complete to (506) 444-5529 or email to pascal.landry@gnb.ca.
- Keep this page for the duration of the test and return with detectors.

Collection

The duration of the test will be 90 days.

- 1) Collect the two detectors after 90 days
- 2) Write the collection date on the detector.
- 3) Write the collection date on the corresponding line below.
- 4) Return the two detectors and this form to:

Att: Pascal Landry

Educational Facilities 250 King Street, Place 2000

Fredericton, NB E3B 9M9

Bliss Carmen Middle School

Room No.	Serial Number	Installation Date day/month/year	Collection Date day/month/year	Result Uncertainty Bq/m³
117	323404	29/01/16	16/05/2016	56 ± 6%
118	269683	27/01/2014	10/04/2014	100
120				
121	269684	27/01/2014	10/04/2014	100
115	323403	29/01/16	16/05/2016	63 ± 6%