

Radon Mitigation Quality Assurance Test

	s test is to assure functionalioned in the community of the community is to be set of the community in the list below the community is the community in the community is the community in the community in the community is the community in the community in the community is the community in the community in the community is the community in the community in the community is the community in the community in the community is the community in the com	•	•	in the building. Two			
Building Information		2640		District ASD-W			
Building Nan		Leo Hayes High So		ICI ASD-W			
Year constru		2000	Phas	e 6			
Tear Constru	ictea	2000	Filas	e 0			
Street Address:		499 Cliffe Street					
City:		Fredericton					
Ventilation S	System Y \ N	Mitig	ation System	Y\N			
				Telephon Numb	er		
Facilities Ma	nager:						
Name of Pers	son Placing Detectors:						
Instructions:							
Installation							
	rooms below, if "R" is indica			om must be tested.			
	etector number on the corres						
	stallation date on the corresp		line.				
	stallation date on the detector		to to (EOC) 444 E	500 ar amail ta			
pascal.landry@	of this sheet after the installa	ation has been comple	ele lo (506) 444-5:	ozy or email to			
	age for the duration of the te	st and return with dete	ectors				
Collection	age for the duration of the te		ion of the test v	will be 90 days			
	two detectors after 90 days	THE durat		Pascal Landry			
· ·	ollection date on the detector	,	Education				
,	ollection date on the correspond			ing Street, Place 2000	,		
4) Return the two detectors and this form to: Fredericton, NB							
			E3B 9	•			
Leo Hayes H	igh School						
Room No.	Serial Number	Installation I		Collection Date	Result	Uncertainty	
A 405		day/month/y	/ear	day/month/year	Bq/m³		
A-105							
A-106	323418	26/01/201	6	24/01/2016	52	52 ± 6%	
A-109							
A-110							
A-116							
A-196							

26/01/2016

24/01/2016

11 ± 12%

323417

D-101