

Radon Mitigation Quality Assurance Test

<p>The goal of this test is to assure functionality of installed radon mitigation systems in the building. Two alternate occupied rooms from the list below will be tested yearly.</p>					
Building Information	2801	District	ASD-W		
Building Name:	Nackawic Senior High School				
Year constructed	1967	Phase	5		
Street Address:	30 Landegger Drive				
City:	Nackawic				
Ventilation System	Y \ N	Mitigation System	Y \ N		
Telephon Number					
Facilities Manager:					
Name of Person Placing Detectors:					
Instructions:					
Installation					
<ol style="list-style-type: none"> 1) Choose two rooms below, if "R" is indicated in front of the room number, this room must be tested. 2) Write the detector number on the corresponding room number line 3) Write the installation date on the corresponding room number line. 4) Write the installation date on the detector (Start Date). 5) Fax a copy of this sheet after the installation has been complete to (506) 444-5529 or email to pascal.landry@gnb.ca. 6) Keep this page for the duration of the test and return with detectors. 					
Collection					
<u>The duration of the test will be 90 days.</u>					
<ol style="list-style-type: none"> 1) Collect the two detectors after 90 days 2) Write the collection date on the detector. 3) Write the collection date on the corresponding line below. 4) Return the two detectors and this form to: 			Att: Pascal Landry Educational Facilities 250 King Street, Place 2000 Fredericton, NB E3B 9M9		
Nackawic Senior High School					
Room No.	Serial Number	Installation Date day/month/year	Collection Date day/month/year	Result Bq/m ³	Uncertainty
A103	323420	03/02/2016	X	Lost	
A104					
A107					
A114					
A123					
A209	323419	03/02/2016	06/06/2016	52 ± 6%	
A216					
C112					
C113					
C117					